SideSaddle Light Mount Instructions

The SideSaddle Light Mount System is designed to be used in 12 ga, TacStar SideSaddles. The light mount will hold the 1" diameter TacStar WLS 2000, or with the use of the supplied nylon bushing; any 1 1/16" diameter Mini Mag size AA flashlight.

1. Remove the 4 slotted screws from the flashlight mount and remove the top half of the ring.
2. Note that one side of the mount is narrower than the other. The narrow side will be towards the shotgun when installed. This will prevent the mount from turning.
3. Place the WLS 2000 on the lower ring half and replace the top ring half. Reinstall and tighten the 4 slotted screws. If a 1 1/16" diameter Mini Mag size light is used, slide the nylon bushing onto the light first, then install as above.
4. Remove the knurled and slotted retaining screw from the bottom of the Light Mount.
5. Slide the Light Mount into the SideSaddle.
6. Reinstall the retaining screw and tighten.
7. Position the flashlight's pressure switch (if used) as desired. Pressure Switch End Cap is available for the Mini Mag Flashlight. Part number 1081196.