

BORE-MAX® SPEED JAGS™ & PATCHES MULTI-CAL PACK


RIFLE

HANDGUN

FASTER RESULTS. LESS EFFORT.

The Bore-Max Speed Jags and Patches Multi-Cal Pack includes 10 popular pistol and rifle calibers in one convenient storage case. Speed Jags and Speed Jag Patches are sized for precise bore fitment and optimal cleaning. The 4X greater bore contact delivers a cleaner bore faster allowing more time at the range.

10 POPULAR HANDGUN AND RIFLE CALIBERS
IN ONE CONVENIENT STORAGE CASE.



INCLUDES SET OF
10 JAGS:


RIFLE

.22 / .223 CAL / 5.56MM
.243 CAL / 6MM
.260 CAL / 6.5MM
.270 CAL, .284 CAL / 7MM
.30 CAL / 7.62MM

INCLUDES
500
SPEED PATCHES

HANDGUN


.22 CAL, .380 CAL / 9MM
.40 CAL, .45 CAL



.22 / .223 CAL / 5.56MM .243 CAL / 6MM .260 CAL / 6.5MM .270 CAL .284 CAL / 7MM .30 CAL / 7.62MM .22 CAL .380 CAL / 9MM .40 CAL .45 CAL

CLEAN BORES FASTER

- Increased surface contact without bunching
- Closer fit for deeper cleaning
- Effectively removes fouling faster




Speed Jag Patch™ & Speed Jag™ vs.
traditional square patch and jag

Only use Speed Jag with the corresponding Speed Jag Patches.

BORE-MAX® SPEED JAGS™ & PATCHES MULTI-CAL PACK

THE BORE-MAX SPEED CLEAN SYSTEM™ IS PRECISELY SIZED FOR MAXIMUM BORE CONTACT.



SPEED JAG PATCH™ - 2X MORE BORE CLEANING CONTACT FOR HANDGUNS AND UPTO 4X FOR RIFLES



WARNING: DO NOT USE SPEED JAG WITH TRADITIONAL PATCHES

Speed Jags and Speed Jag Patches are sized exactly to work in tandem delivering precise bore fitment by caliber. As a result, use of any other patch or jag with Bore-Max Speed Clean System components may result in the jag getting trapped in the bore.

ONLY USE Speed Jag Patches with the corresponding Speed Jag.

DO NOT USE Speed Jag Patches on regular jags.

Always make sure your firearm is unloaded prior to cleaning.

1. Add Bore-Max Bore Solvent to your bore at the breach. Point muzzle slightly downward (let it work for 10 – 15 minutes).
2. Use Bore-Max Speed Brush™ to vigorously scrub the inside of the bore, breach to muzzle, to agitate the fouling.
3. Drape Speed Jag Patch over Speed Jag™ evenly, ensuring it covers the jag on both sides.
4. Run Speed Jag and Patch through the bore (breach to muzzle). Continue repeating this step with a fresh patch until the patch is clear of fouling residue.
5. Fouling is removed in layers, so repeat steps 1 through 4 until all fouling is clear (indicated by a clear patch on the first pass in step 4).

⚠ WARNING: This product can expose you to chemicals including Nickel (Metallic), which is known to the state of California to cause cancer and birth defects or reproductive harm. For more information, go to www.P65Warnings.ca.gov.



5480 NATHAN LANE NORTH, SUITE 120
MINNEAPOLIS, MN 55442 800.286.0567
info@realavid.com | **RealAvid.com**
© 2023 NEW REVO BRAND GROUP, LLC

