

## POWERFUL COPPER & CARBON ELIMINATOR

Powerful gun-metal grade foaming solvent is specially formulated to expand and penetrate within the gun bore, rapidly and effectively dissolving performance inhibiting copper and powder fouling.



**Powerful gun-metal grade foaming solvent expands and penetrates to rapidly dissolve copper & powder fouling.**

- Shake can before use.
- Use a bore brush to scrub the bore before application.
- Spray fast expanding foam into barrel from the breech.
- Spray foam carefully in short bursts allowing the foam to fill the barrel.
- Keep muzzle in a slightly lowered position to keep cleaning residue from entering the receiver and allowing dissolved fouling to run out end of barrel.
- Wait 10-15 minutes and then use a cleaning rod and patches to remove all foam and fouling from barrel.
- Foam will turn blue to indicate dissolved copper and black to indicate powder removal.
- For heavy copper build-up, repeat the process.
- After cleaning, apply Gun-Max Gun Oil to bore to protect against corrosion.

Make sure firearm is fully unloaded and bore is free of any obstruction.

***For use in bore only. Do not apply to rubber, polymer or wood parts or painted or dipped finishes. Wipe off immediately with a cloth to avoid damage.***

 **WARNING:** This product can expose you to chemicals including n-methyl-2-pyrrolidone, which is known to the state of California to cause cancer and birth defects or reproductive harm. For more information, go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).



5480 NATHAN LANE NORTH, SUITE 120  
MINNEAPOLIS, MN 55442 800.286.0567  
[info@realavid.com](mailto:info@realavid.com) | [RealAvid.com](http://RealAvid.com)  
© 2021 NEW REVO BRAND GROUP, LLC.

